

# REPLACEMENT COILS



## A591-011B

13/16"-20  
Internal Thread  
1.25"dia X 10.8" lg

I, III, V,  
CD1, CD2,  
CPU-90, CPU-96,  
DISN



## A591-011A

13/16"-20  
Internal Thread  
1.25"dia X 6.1" lg

I, III, V,  
CD1, CD2,  
CPU-90, CPU-96,  
DISN



## A591-018

3-bolt Flange  
Mount, Blue  
2.38" dia X 6.3"lg.

I, III,  
CD1, CD2,  
CPU-90, CPU-96,  
DISN



501-061 or 69694  
New # **330-2-AI-46**

Blue Epoxy  
2.38" dia X 5.9" lg

I, III, V,  
CD1, CD2,  
CPU-90, CPU-96,  
DISN

## A501-061S

Steel Can/  
Blue Epoxy  
2.25"dia X 6.6" lg

I, III, V,  
CD1, CD2,  
CPU-90, CPU-96,  
DISN



## A591-010S

Steel Can/  
Red Epoxy  
2.25"dia X 6.6" lg

I, III,  
CD1, CD2,  
CPU-90, CPU-96,  
DISN

**ARROW ENGINE COMPANY**

2301 East Independence, Tulsa, Oklahoma 74110

toll free 800 331-3662 local 918 583-5711 toll free fax in US & Canada 800 266-1481 fax 918-388-3202 www.arrowengine.com